

9/15/11 Mohawk Rubber Sales TPMS APPL. GUIDE

MAKE	MODEL	YEAR	REPL. SENSOR	Torq	KIT #	E-Z SENSOR	Redi Sensor	Orange
ACURA	CSX	2008-09	1212	35	2040K			HOSNAA83
ACURA	MDX	2004- 06	28981****	35	2000K/ 20036			HOS3VA04
ACURA	MDX	2007- 11	1209	35	1100K			HOSTKA03
ACURA	RDX	2007-11	1209	35	1100K			HOSTKA03
ACURA	RL	05-'08	1057	35	2000K/ 20036			HOS3VA04
ACURA	RL	2009-10	1211	35	2040K			
ACURA	RL	2009-10	1057****	35	2000K/ 20036			HOSHJA53
*Note: Use TRW Accelerpmeter Enable Function on Bartec WRT400 w/ 1057								
ACURA	TL	2006- 08	28981****	35	2000K/ 20036			HOS3VA04
ACURA	TL (Hi-Line)	2009-11	1214	353	2040K			
ACURA	TSX	2007-08	1209	35	1100K			HOSTKA03
ACURA	TSX	2009-10	1209	35	1100K			
ACURA	ZDX (Hi-Line)	2010	1214	35	2040K			
ALFA ROMEO		2006	28981****		2000K/ 20036			HOS3VA07
AUDI	ALLROAD (315 Mhz)	01-'05	59.0157	35	*			SPB10B
AUDI	A3 (315 MHz)	2006-11	1053	71	1030K			SI253D
AUDI	A4 (433 MHz)	2002-08	59.0158	35	*			SPB10A
AUDI	A4 (315 MHz)	2009-10	1053	71	1030K			SI253D
AUDI	A5 (315 MHz)	2008-10	1053	71	1030K			SI253D
AUDI	A6 ALLROAD (433 Mhz)	01-'06	59.0151	35				SPB10A
AUDI	A6 ALLROAD (433 MHz)	2007-'09	59.0158	35	*			SPB10A
AUDI	A6 ALLROAD (433 MHz)	2010	9011/BERU	35	*			SPB10A
AUDI	A6	2002-'04	59.0157	35	*			SPB10B
AUDI	A6	2005-'09	59.0158	35	*			SPB10A
AUDI	A6	2010-11	9011/BERU	35	*			SPB10A
AUDI	A8 (433MHz)	2000-11	59.0151	35	*			SPB10A
AUDI	A8 (315 MHz)	2001- '07	59.0157	35	*			SPB10B
AUDI	Q5	2009-11	1053	71	1030K			SI253D
AUDI	Q7	2005- '09	59.0158	35	*			SPB10A
AUDI	Q7	2010-11	9011/BERU	35	*			SPB10A
AUDI	R8	2008-09	59.0158	35	*			SPB10A
AUDI	R8	2010-11	9011/BERU	35	*			SPB10A
AUDI	RS4	2007- '09	59.0158	35	*			SPB10A
AUDI	RS6/ RS6 PLUS (315 MHz)	2001 - '05	59.0157	35	*			SPB10B
AUDI	RS6/ RS6 PLUS (433 MHz)	2001 - '05	59.0151	35	*			SPB10A
AUDI	S4	02-'08	59.0158	35	*			SPB10A
AUDI	S4 (315 MHz)	2010-11	1053	71	1030K			SI253D
AUDI	S5 (315 MHz)	2008-11	1053	71	1030K			SI253D
AUDI	S6	04-'09	59.0158	35	*			SPB10A
AUDI	S6	2010-11	9011/BERU	35	*			SPB10A
AUDI	S8 (315MHz)	2001-07	59.0157	35	*			SPB10B
AUDI	S8 (433MHz)	2000-09	59.0151	35	*			SPB10A
AUDI	TT (315 MHz)	2008-11	1053	71	1030K			SI253D
BENTLEY	CONTINENTAL GT	03-'05	59.0151	35	*			SPB10A
BENTLEY	CONTINENTAL GT	06- '10	59.0158	35	*			SPB10A
BMW	ALPINA	2004-08	59.0152	35	*			SPB10A
BMW	1 SERIES	2007-'10	1027	35	*			SPB10A
BMW	1 SERIES	09/10+	9012	35	*			
BMW	SERIES 3 (315Mhz)	2000-02	59.0157	35	*			SPB10B
BMW	SERIES 3	03/99- 06	59.0152	35	59.0307			
BMW	SERIES 3	2007- '10	1027	35	*			SPB10A
BMW	SERIES 3	09/2009+	9012	35	*			SPB10A
BMW	SERIES 5	09/98- 05	59.0152	35	*			SPB10A
BMW	SERIES 5 (315 Mhz)	2000-'02	59.0157	35	*			SPB10B
BMW	SERIES 5	2006-10	1027	35	*			SPB10A
BMW	SERIES 5	09/10+	9012	35	*			SPB10A
BMW	SERIES 6	2006-10	1027	35	*			SPB10A

MAKE	MODEL	YEAR	REPL. SENSOR	Torq	KIT #	E-Z SENSOR	Redi Sensor	Orange
BMW	SERIES 7 (315 Mhz)	2000-01	59.0157	35	*			SPB10B
BMW	SERIES 7	2002- 05	59.0152	35	*			SPB10A
BMW	SERIES 7	2006-10	1027	35	*			SPB10A
BMW	SERIES 7	09/10-	9012					SPB10A
BMW	M SERIES	2003-10	1027	35	*			SPB10A
BMW	M SERIES	09/09-11	9012	35	*			SPB10A
BMW	X3	2006-10	1027	35	*			SPB10A
BMW	X4	2011	9012	35	*			SPB10A
BMW	X5	2001-04	59.0153	35	*			SPB10A
BMW	X5	2005-10	1027	35	*			SPB10A
BMW	X5	10/2010+	9012	35	*			SPB10A
BMW	X6	2008-11	1027	35	*			SPB10A
BMW	X6	10/2010+	9012	35	*			SPB10A
BMW	Z SERIES	2006-11	1027	35	*			SPB10A
BMW	Z SERIES	09/2010+	9012	35	*			SPB10A
BUGATTI	VEYRON	2005-06	N/A		1090K			
BUICK	ALLURE	2007 - 08	20158	62	1070K	33000	7001	SI1013
BUICK	ALLURE	2009 -10	20153		VS-950	33000	7001	SC4101
BUICK	ENCLAVE	2008	20158	62	1070K	33000	7001	SI1013
BUICK	ENCLAVE	2009-11	20153		VS-950	33000	7001	SC4101
BUICK	LACROSSE	2007 - 08	20158	62	1070K	33000	7001	SI1013
BUICK	LACROSSE	2009 -11	20153		VS-950	33000	7001	SC4101
BUICK	LE SABRE	2007	20153		VS-950	33000	7001	SC4101
BUICK	LUCERNE	2007- 11	20153		VS-950	33000	7001	SC4101
BUICK	RAINER - OE# 25774006	2006- '07	20116	62	1070K		7001	SC4006
BUICK	RAINER - OE# 25799331	Late 2007	20153		VS-950	33000	7001	SC4101
BUICK	REGAL	2011	20153		VS-950	33000	7001	SC4101
CADILLAC	CTS	2004- 07	20116	62	1070K		7001	SC4006
CADILLAC	CTS	2008-11	20153		VS-950	33000	7001	SC4101
CADILLAC	CTS-V	2009-11	20158	62	1070K	33000	7001	SI1013
CADILLAC	DEVILLE	01-'05	20117		1080K		7001	SC3946
CADILLAC	DTS	2006	20158	62	1070K	33000	7001	SI1013
CADILLAC	DTS	2007- 11	20153		VS-950	33000	7001	SC4101
CADILLAC	ESCALADE	2004	20115	62	1070K			SC2575
CADILLAC	ESCALADE	05-'06	20107	62	1070K			SC4379
CADILLAC	ESCALADE	2007-10	20153		VS-950	33000	7001	SC4101
CADILLAC	ESCALADE ESV	2004	20115	62	1070K			SC2575
CADILLAC	ESCALADE ESV	05-'06	20107	62	1070K			SC4379
CADILLAC	ESCALADE ESV	2007-11	20153		VS-950	33000	7001	SC4101
CADILLAC	ESCALADE EXT	2004	20115	62	1070K			SC2575
CADILLAC	ESCALADE EXT	05-'06	20107	62	1070K			SC4379
CADILLAC	ESCALADE EXT OE#15825475	EARLY 2007	N/A	62	2020K		7001	SC8606
CADILLAC	ESCALADE EXT	2007- '11	20153		VS-950	33000	7001	SC4101
CADILLAC	SEVILLE	01-'04	20117	62	1080K		7001	SC3946
CADILLAC	SRX	04-'06	20116	62	1070K		7001	SC4006
CADILLAC	SRX	2007-'11	20153		VS-950	33000	7001	SC4101
CADILLAC	STS	2005-'08	20076	62	1070K		7001	SC8220
CADILLAC	STS	2009	20158	62	1070K	33000	7001	SI1013
CADILLAC	STS	2009-11	20153		VS-950	33000	7001	SC4101
CADILLAC	XLR	04-'09	20076	62	1070K		7001	SC8220
CHEVEROLET	AVALANCHE	2004	20115	62	1070K			SC2575
CHEVEROLET	AVALANCHE - OE#15136883	05-'06	20115	62	1070K			SC2575
CHEVEROLET	AVALANCHE - OE#15114379	05-'06	20107	62	1070K			SC4379
CHEVEROLET	AVALANCHE	2007	20158	62	1070K	33000	7001	SC8606
CHEVEROLET	AVALANCHE	2007-'11	20153		VS-950	33000	7001	SC4101
CHEVEROLET	AVEO	2008-11	20153		VS-950	33000	7001	SC4101
CHEVEROLET	CAMARO	2010-2011	20153		VS-950	33000	7001	SC4101
CHEVEROLET	COBALT	2008-09	20158	62	1070K	33000	7001	SC8606
CHEVEROLET	COBALT	2008-09	20153	62	VS-950	33000	7001	SC4101

MAKE	MODEL	YEAR	REPL. SENSOR	Torq	KIT #	E-Z SENSOR	Redi Sensor	Orange
CHEVEROLET	COBALT	2010-11	20153	62	VS-950	33000		SC8826
CHEVEROLET	COLORADO	2007-11	20131	62	1070K			SC2618
CHEVEROLET	CORVETTE	97-'00	28006	62	20012			
CHEVEROLET	CORVETTE	01-'04	20117	62	1080K		7001	SC3946
CHEVEROLET	CORVETTE	05-'09	20076	62	1070K		7001	SC8220
CHEVEROLET	CORVETTE	2010-11	20158	62	1070K	33000	7001	SC8606
CHEVEROLET	EQUINOX	2007-'09	20158	62	1070K	33000	7001	SI1013
CHEVEROLET	EQUINOX	2010-11	20153		VS-950	33000	7001	SC4101
CHEVEROLET	EXPRESS	2008-09	20158	62	1070K	33000	7001	SI1013
CHEVEROLET	EXPRESS	2010-11	20153		VS-950	33000	7001	SC4101
CHEVEROLET	G SERIES VAN	2008	20158	62	1070K	33000	7001	SI1013
CHEVEROLET	HHR	2008-09	20158	62	1070K	33000	7001	SC8606
CHEVEROLET	HHR - OE#25920615	2008-11	20153		VS-950	33000	7001	SC4101
CHEVEROLET	HHR	2010-11	20153		VS-950	33000	7001	SC8606
CHEVEROLET	IMPALA	06-'07	20158	62	1070K	33000	7001	SC8606
CHEVEROLET	IMPALA	2007-11	20153		VS-950	33000	7001	SC4101
CHEVEROLET	MALIBU OE# 15921013 <10/07	2008	20158	62	1070K	33000	7001	SI1013
CHEVEROLET	MALIBU	2008-09	20153		VS-950	33000	7001	SC4101
CHEVEROLET	MALIBU	2010-11	20153		VS-950	33000	7001	SC8606
CHEVEROLET	MONTE CARLO - alum	06-'07	20158	62	1070K	33000	7001	SC8606
CHEVEROLET	MONTE CARLO - rubber	06-'07	20153		VS-950	33000	7001	SC4101
CHEVEROLET	SILVERADO	2004	20115	62	1070K			SC2575
CHEVEROLET	SILVERADO	05-'06	20107	62	1070K			SC4379
CHEVEROLET	SILVERADO OE# 15825475	2007	N/A	62	2020K	33000		SC8606
CHEVEROLET	SILVERADO	2007-'11	20153		VS-950	33000	7001	SC4101
CHEVEROLET	SSR	2006-'07	20116	62	1070K		7001	SC4006
CHEVEROLET	SUBURBAN	2004	20115	62	1070K			SC2575
CHEVEROLET	SUBURBAN	05-'06	20107	62	1070K			SC4379
CHEVEROLET	SUBURBAN OE# 15825475	2007	N/A	62	2020K	33000	7001	SC8606
CHEVEROLET	SUBURBAN	2007-'11	20153		VS-950	33000	7001	SC4101
CHEVEROLET	TAHOE	2004	20115	62	1070K			SC2575
CHEVEROLET	TAHOE	05-'06	20107	62	1070K			SC4379
CHEVEROLET	TAHOE OE# 15825475	2007	N/A	62	2020K	33000	7001	SC8606
CHEVEROLET	TAHOE	2007-'11	20153		VS-950	33000	7001	SC4101
CHEVEROLET	TRAILBLAZER	06-'09	20116	62	1070K		7001	SC4006
CHEVEROLET	TRAVERSE	2009-11	20153		VS-950	33000	7001	SC4101
CHEVEROLET	UPLANDER	2008-09	20158	62	1070K	33000	7001	SC8606
CHEVEROLET	VOLT	2010-11	20153		VS-950	33000	7001	SC4101
CHRYSLER	200	11	1051	71	1050K		7001	SC36AA
CHRYSLER	200	11	20066	71	2030K - Kit 20020- Valve	33000	7001	SC36AA
CHRYSLER	300	05-'07	1051	71	1050K		7001	SC36AA
CHRYSLER	300	05-'07	20066	71	2030K - Kit 20020- Valve		7001	SC36AA
	**USE 1050K REBUILD KIT ON SIEMENS SENSOR/ 2030K ON SCHRADER							
CHRYSLER	300	2008	1043	71	1050K		7004	SI1698
CHRYSLER	300 (433 MHz)	2009-10	28214	53	2030K - Kit 20020- Valve			SC9400
CHRYSLER	300 - ALLOY WHEELS	2010-11	9398		VS-950			
CHRYSLER	300M	2002-04	20028	35	1080K	33100	7004	SC90AC
CHRYSLER	ASPEN	2007-09	1051/ 20066	71	1050K/ 2030K	33000	7001	SC36AA
CHRYSLER	ASPEN	2007-09	20066	71	2030K - Kit 20020- Valve		7001	SC36AA
CHRYSLER	CONCORDE	02-04	20028	35	1080K	33100	7004	SC90AC
CHRYSLER	CROSSFIRE	04-'05	20028	35	1080K	33100	7004	SC90AC
CHRYSLER	CROSSFIRE OE#56053030AB	06-'08	1051/ 20066	71	1050K/ 2030K	33000	7001	SC36AA
CHRYSLER	CROSSFIRE OE#5208990AC	06-'08	20028	35	1080K	33100	7004	SC90AC
CHRYSLER	PACIFICA	02-'03	20028	35	1080K	33100	7004	SC90AC
CHRYSLER	PACIFICA	04-'05	1052	71	1050K		7001	SI35AD
CHRYSLER	PACIFICA	06-'08	1051	71	1050K		7001	SC36AA

MAKE	MODEL	YEAR	REPL. SENSOR	Torq	KIT #	E-Z SENSOR	Redi Sensor	Orange
	**USE 1050K REBUILD KIT ON SIEMENS SENSOR/ 2030K ON SCHRADER							
CHRYSLER	PROWLER	2002	20028	35	1080K	33100	7004	SC90AC
CHRYSLER	PT CRUISER	2008-10	1051	71	1050K/ 2030K		7001	SC36AA
	**USE 1050K REBUILD KIT ON SIEMENS SENSOR/ 2030K ON SCHRADER							
CHRYSLER	SEBRING (315 MHz)	07-'10	1051	71	1050K/ 2030K		7001	SC36AA
	**USE 1050K REBUILD KIT ON SIEMENS SENSOR/ 2030K ON SCHRADER							
CHRYSLER	SEBRING (433 MHz)	08-'09	1043/DILL	71	1050K		7004	SI1698
CHRYSLER	TOWN & COUNTRY	02-'03	20028	35	1080K	33100	7004	SC90AC
CHRYSLER	TOWN & COUNTRY	04-'05	1052	71	1050K		7001	SI35AD
CHRYSLER	TOWN & COUNTRY	06-'08	1051	71	1050K		7001	SC36AA
CHRYSLER	TOWN & COUNTRY (433 MHz)	2008-11	1043	71	1050K		7004	SI1698
CHRYSLER	TOWN & COUNTRY (433 MHz)	2011	9398	71	VS-950			
CHRYSLER	VOYAGER	02-'03	20028	35	1080K	33100	7004	SC90AC
DODGE	AVENGER	2008-10	1051	71	1050K		7001	SC36AA
DODGE	CALIBER	2007-'11	1051	71	1050K		7001	SC36AA
DODGE	CARAVAN	02-'03	20028	35	1080K	33100	7004	SC90AC
DODGE	CARAVAN	04-'05	1052	71	1050K		7001	SI35AD
DODGE	CARAVAN	06-'07	1051	71	1050K		7001	SC36AA
	**USE 1050K REBUILD KIT ON SIEMENS SENSOR/ 2030K ON SCHRADER							
DODGE	CHALLENGER (433 Mhz)	2008	1043	71	1050K		7004	SI1698
DODGE	CHALLENGER - SRT (433Mhz)	2009-11	28214	53	2030K			SC9400
DODGE	CHALLENGER - ALLOY	2010-11	9398		VS-950			
DODGE	CHARGER	06-'07	1051	71	1050K/ 2030K		7001	SC36AA
	**USE 1050K REBUILD KIT ON SIEMENS SENSOR/ 2030K ON SCHRADER							
DODGE	CHARGER	2008	1043		1050K		7004	SI1698
DODGE	CHARGER - SRT (433 Mhz)	2009-11	28214	53	2030K			SC9400
DODGE	CHARGER - ALLOY	2010-11	9398		VS-950			
DODGE	DAKOTA	2008-10	9154	53	2030K	33000	7001	
DODGE	DAKOTA	2011	9308		VS-950		7001	
DODGE	DAKOTA	2011	1051	71	1050K		7001	SC36AA
DODGE	DURANGO	07-'09	1051/ 20066	71	1050K/ 2030K	33000	7001	SC36AA
	**USE 1050K REBUILD KIT ON SIEMENS SENSOR/ 2030K ON SCHRADER							
DODGE	DURANGO	2011	9398		VS-950			
DODGE	GRAND CARAVAN	02-'03	20028	35	1080K	33100	7004	SC90AC
DODGE	GRAND CARAVAN	04-'05	1052	71	1050K		7001	SI35AD
DODGE	GRAND CARAVAN	06-'07	1051	71	1050K/ 2030K		7001	SC36AA
	**USE 1050K REBUILD KIT ON SIEMENS SENSOR/ 2030K ON SCHRADER							
DODGE	GRAND CARAVAN (433MHz)	2008-11	1043	71	1050K		7004	SI1698
DODGE	INTREPID	02-'04	20028	35	1080K	33100	7004	SC90AC
DODGE	JOURNEY	2009-11	1043	71	1050K		7004	SI1698
DODGE	MAGNUM	05-'07	1051	71	1050K		7001	SC36AA
DODGE	MAGNUM (433MHz)	2008	1043	71	1050K		7004	SI1698
DODGE	MAGNUM (433MHz)	2009	28214	53	2030K			SC9400
DODGE	NITRO	2007-11	1051/ 20066	71	1050K/ 2030K		7001	SC36AA
	**USE 1050K REBUILD KIT ON SIEMENS SENSOR/ 2030K ON SCHRADER							
DODGE	NITRO	2010-11	9308		VS-950		7001	
DODGE	RAM	2008-09	9154	53	2030K	33000		
DODGE	RAM (433Mhz)	2009	1043	71	1050K		7004	SI1698
DODGE	RAM (433Mhz)	2010-11	9398		VS-950			
DODGE	SPRINTER	2007-10	1042	54	1098K			
DODGE	STRATUS	2007	1051	71	1050K		7001	SC36AA
DODGE	VIPER	03-'10	20028	35	1080K	33100	7004	SC90AC
FERRARI	430 (433Mhz)	2006-07	59.0151					
FERRARI	430 (433Mhz)	2008-11	59.0158					
FERRARI	458	2010-11	9008/BERU		*			
FERRARI	550-575-612-SPIDER	02-'09	59.0151		*			SPB10A
FERRARI	CALIFORNIA (433 Mhz)	2010	9008/BERU		*			
FERRARI	ENZO-FXX	03-'09	59.0156		*			SPB10A
FERRARI	575 (315 Mhz)	2002-05	59.0157		*			SPB10A

MAKE	MODEL	YEAR	REPL. SENSOR	Torq	KIT #	E-Z SENSOR	Redi Sensor	Orange
FERRARI	Spider (433Mhz)	2002-09	59.0151					SPB10A
FORD	500	2008-09	1048/5105***		**	33000	7001	LE6L2T
FORD	CROWN VICTORIA	2006-11	1048/5105***		**	33000	7001	LE6L2T
FORD	E SERIES	2010-11	20315		VS-950	33000	7001	SC9L2T
FORD	E150	2007	1048/5105***		**	33000	7001	LE6L2T
FORD	EDGE	2007-10	1048/5105***		**	33000	7001	LE6L2T
FORD	EDGE	2011	20315		VS-950	33000	7001	SC9L2T
FORD	ESCAPE	2006-08	1048/5105***		**	33000	7001	LE6L2T
FORD	ESCAPE	2009-11	20315		VS-950	33000	7001	SC9L2T
FORD	EXPEDITION	03-'04	20096	44	1060K	33100	7004	SC50BA
FORD	EXPEDITION	05-'06	20135	44	1060K		7001	SC9L2T
FORD	EXPEDITION	2007-10	1048/5105***		**	33000	7001	LE6L2T
FORD	EXPEDITION	2011	20315		VS-950	33000	7001	SC9L2T
FORD	EXPLORER	03-'05	20096	44	1060K	33100	7004	SC50BA
FORD	EXPLORER	2006-10	1048/5105***		**	33000	7001	LE6L2T
FORD	EXPLORER	2011	20315		VS-950	33000	7001	SC9L2T
FORD	F150	2007-09	1048/5105***		**	33000	7001	LE6L2T
FORD	F150	2009-10	20315		VS-950	33000	7001	SC9L2T
FORD	FIESTA	2011	20315		VS-950	33000	7001	SC9L2T
FORD	FLEX	2009-10	1048/5105***		**	33000	7001	LE6L2T
FORD	FLEX	2011	20315		VS-950	33000	7001	SC9L2T
FORD	FOCUS	2007-09	1048/5105***		**	33000	7001	LE6L2T
FORD	FOCUS	2010-11	20315		VS-950		7001	SC9L2T
FORD	FREESTAR	2004-05	20135	44	1060K		7001	SC9L2T
FORD	FREESTAR	2006-10	1048/5105***		**	33000	7001	LE6L2T
FORD	FUSION	2009-10	1048/5105***		**	33000	7001	LE6L2T
FORD	FUSION	2010-11	20315		VS-950	33000	7001	SC9L2T
FORD	MUSTANG	2007-09	1048/5105***		**	33000	7001	LE6L2T
FORD	MUSTANG	2010-11	20315		VS-950	33000	7001	SC9L2T
FORD	RANGER	2007-11	1048/5105***		**	33000	7001	LE6L2T
FORD	SPORTRAC	2006-10	1048/5105***		**	33000	7001	LE6L2T
FORD	SUPER DUTY	2010-11	20315		VS-950	33000	7001	SC9L2T
FORD	E SERIES, SUPER DUTY	2007-09	1048-HP		**			LE8C2T
FORD	F250,F350, HD MODELS	2007- 05/09	1048-HP		**			LE8C2T
FORD	F250,F350, HD MODELS	06/09 -'11	20315		VS-950	33000	7001	SC9L2T
FORD	TAURUS	2008-10	1048/5105***		**	33000	7001	LE6L2T
FORD	TAURUS - Post May 2010	2011	20315		VS-950	33000	7001	SC9L2T
FORD	TRANSIT	2010-11	20315		VS-950	33000	7001	SC9L2T
*Redi-Sensor relearn must be performed with scan tool and not magnet								
GMC	ACADIA	2007-'08	20158	62	1070K	33000	7001	SI1013
GMC	ACADIA	2009-11	20153		VS-950	33000	7001	SC4101
GMC	CANYON	2007- 10	20131	62	1110K			SC2618
GMC	ENVOY	2005- '07	20116	62	1070K		7001	SC4006
GMC	ENVOY	2007-09	20153		VS-950	33000	7001	SC4101
GMC	SAVANA	2008-09	20158	62	1070K	33000	7001	SI1013
GMC	SAVANA	2010-11	20153		VS-950	33000	7001	SC4101
GMC	SIERRA	2004	20115	62	1070K			SC2575
GMC	SIERRA	05-'06	20107	62	1070K			SC4379
GMC	SIERRA (ALL)	2007	20158	62	1070K	33000	7001	SI1013
GMC	SIERRA - OE# 15825475	2007	N/A		2020K		7001	SC8606
GMC	SIERRA (ALL)	2007-'11	20153		VS-950	33000	7001	SC4101
GMC	TERRAIN	2010-11	20153		VS-950	33000	7001	SC4101
GMC	YUKON	2004	20115	62	1070K			SC2575
GMC	YUKON	05-'06	20107	62	1070K			SC4379
GMC	YUKON	2007	20158	62	1070K	33000	7001	SI1013
GMC	YUKON (ALL)	2007-'10	20153		20018	33000	7001	SC4101
HONDA	ACCORD	2008-11	1208	35	1100K	33000		HSOWA306
HONDA	CIVIC	2008-11	1212	35	2040K	33000		HOSNAA83
HONDA	CRV OE# 42753-SWA-316	2007-11	1208	35	1100K	33000		HSOWA306

MAKE	MODEL	YEAR	REPL. SENSOR	Torq	KIT #	E-Z SENSOR	Redi Sensor	Orange
HONDA	CROSSTOUR	2010-11						
HONDA	ELEMENT	2006-'08	1058	35	2000K/ 20036			HOSCVA01
HONDA	ELEMENT	2009-11	1212	35	2040K	33000		HOSNAA83
HONDA	FIT	2008	1208	35	1100K	33000		HSOWA306
HONDA	FIT	2009-11	1212	35	2040K	33000		HOSNAA83
HONDA	INSIGHT	2010-11	1212	35	2040K	33000		HOSNAA83
HONDA	ODYSSEY - BASIC	2007	1058	35	2000K/ 20036			HOSCVA01
HONDA	ODYSSEY - BASIC	2008-10	1058	35	2000K/ 20036			HOSHJA82
Note: Use "TRW Accelerometer Enable" function on Bartec WRT400 tool to activate sensor on this model								
HONDA	ODYSSEY - TOURING	2005-07	1057	35	2000K/ 20036			HOS3VA04
HONDA	ODYSSEY - TOURING	2008-10	1057	35	2000K/ 20036			HOSHJA53
Note: Use "TRW Accelerometer Enable" function on Bartec WRT400 tool to activate sensor on this model								
HONDA	ODYSSEY	2011	1212	35	2040K	33000		HOSNAA83
HONDA	ODYSSEY- TOURING	2011	1212	35	2040K	33000		HOSNAA83
HONDA	PILOT - ALLOY	05-'08	28981****	35	2000K/ 20036			HOS3VA04
HONDA	PILOT - STEEL	05-'08	28982****	35	2000K/ 20035			HOS9VA03
HONDA	PILOT	2009-11	1209	35	1100K			HOSTKA03
HONDA	RIDGELINE RT	06-'08	28982****	35	2000K/ 20035			HOS9VA03
HONDA	RIDGELINE RTL	05-'07	28981****	35	2000K/ 20036			HOS3VA04
HONDA	RIDGELINE RTS	05-'07	28981****	35	2000K/ 20036			HOS3VA04
HONDA	RIDGELINE RTX	06-'08	28982****	35	2000K/ 20035			HOS9VA03
HONDA	RIDGELINE (ALLOY)	2009-10	1211	35	2040K			HOS3VA04
HONDA	RIDGELINE (ALLOY)	2009-11	1057	35	2000K/ 20036			HOSHJA53
Note: Use "TRW Accelerometer Enable" function on Bartec WRT400 tool to activate sensor on this model								
HONDA	S2000	2008-10	N/A	35	1100K			HOS2A315
HUMMER	HUMMER H2	2008-10	20153		VS-950	33000	7001	SC4101
HUMMER	HUMMER H3	06-'10	20131	62	1110K			SC2618
HUMMER	HUMMER H3T	2009-10	20131	62	1110K			SC2618
HYUNDAI	ACCENT	06-'07	28983	31-40	2000K			
HYUNDAI	ACCENT	08-'10	1206-A	31-40	1100K			HY2F000
Note: Use "TRW Accelerometer Enable" function on Bartec WRT400 tool to activate sensor on this model								
HYUNDAI	AZERA	2007-11	1068	31-40	59.0340			HY2G200
HYUNDAI	ELANTRA	2007-11	1068	31-40	59.0340			HY2G200
HYUNDAI	ELANTRA (TOURING)	2010-11	5507	80	1050K		7001	
HYUNDAI	ENTOURAGE	2007-11	1028	31-40	2000K/ 20036			
HYUNDAI	EQUIUS	2011	1206-A	31-40	2040K			HY2F000
Note: Use "TRW Accelerometer Enable" function on Bartec WRT400 tool to activate sensor on this model								
HYUNDAI	GENESIS (HL)	2009-10	1206-A	31-40	2040K			HY2F000
HYUNDAI	GENESIS COUPE	2010-11	5507				7001	
HYUNDAI	GRANDEUR	2007	1028	31-40	2000K/ 20036			
HYUNDAI	SANTA FE (Lo-Line)	2007-'08	1028	31-40	2000K/ 20036			HY4D200
HYUNDAI	SANTA FE (Hi-Line)	2008-10	1068	31-40	2000K/ 20036			HY2G200
Note: Use "TRW Accelerometer Enable" function on Bartec WRT400 tool to activate sensor on this model								
HYUNDAI	SANTA FE 10/2009 +	2010-11	1068					
HYUNDAI	SONATA	2007-08	28983	31-40	2000K			HY1F000
HYUNDAI	SONATA	2008-10	1206-A	31-40	2040K			HY2F000
Note: Use "TRW Accelerometer Enable" function on Bartec WRT400 tool to activate sensor on this model								
HYUNDAI	SONATA	2011	5507				7001	
HYUNDAI	TERRACAN	2007	1028	31-40	2000K/ 20036			
HYUNDAI	TIBURON	2007-08	28983	31-40	2000K			HY1FA00
HYUNDAI	TUCSON	07-'10	28983	31-40	2000K			HY1FA00
HYUNDAI	TUCSON	2010-11	1206-A	31-40	2040K			HY2F000
HYUNDAI	VERAVRUZ (Lo-Line)	2006-08	1028	31-40	2000K/ 20036			
HYUNDAI	VERAVRUZ (Hi-Line)	2008-11	1068	31-40	59.0340			HY2G200
INFINITI	EX35	2008	20064	45-60	1080K	33000		SCD001
INFINITI	EX35	2009-10	28204	66	2030K	33000	7001	SCA01B
INFINITI	EX35	2011	1216		1100K			
INFINITI	FX35	03-'08	20064	45-60	1080K	33000		SCD001
INFINITI	FX35	2009-10	28204	66	2030K	33000	7001	SCA01B

MAKE	MODEL	YEAR	REPL. SENSOR	Torq	KIT #	E-Z SENSOR	Redi Sensor	Orange
INFINITI	FX35	2011	1216		1100K			
INFINITI	FX45	03-'08	20064	45-60	1080K	33000		SCD001
INFINITI	FX50	2009-10	28204	66	2030K	33000	7001	SCA01B
INFINITI	FX50	2011	1216		1100K			
INFINITI	G35	03-'06	20064	45-60	1080K	33000		SCD001
INFINITI	G35	2007-08	28204	66	2030K	33000	7001	SCA01B
INFINITI	G35	2011	1216		1100K			
INFINITI	G37	2008-10	28204	66	2030K	33000	7001	SCA01B
INFINITI	M35	2006-'07	20064	45-60	1080K	33000		SCD001
INFINITI	M35	2008-10	28204	66	2030K	33000	7001	SCA01B
INFINITI	M35	2011	1216		1100K			
INFINITI	M37	2011	1216		1100K			
INFINITI	M45	03-'07	20064	45-60	1080K	33000		SCD001
INFINITI	M45	2008-10	28204	66	2030K	33000	7001	SCA01B
INFINITI	M45	2011	1216		1100K			
INFINITI	M56	2011	1216		1100K			
INFINITI	Q45 (Pre- July)	03-'06	20064	45-60	1080K	33000		SCD001
INFINITI	Q45 (Post August)	2006	28204	66	2030K	33000	7001	SCA01B
INFINITI	QX4	2003	20064	45-60	1080K	33000		SCD001
INFINITI	QX56 (ALLOY)	04-'07	20161	49	1080K	33000		SCK001
INFINITI	QX56 (STEEL)	2005-'06	20069	49	1130K	33000		SCK001
INFINITI	QX56	2007-10	28204	66	2030K	33000	7001	SCA01B
INFINITI	QX56	2011	1216		1100K			
ISUZU	ASCENDER	06-'08	20116	62	1070K		7001	SC4006
ISUZU	I SERIES	2007-08	20131	62	1100K			SC2618
ISUZU	RODEO	2004	20028	35	1080K	33100	7004	SC90AC
JAGUAR	S (315 MHz)	2005-09	1055	71	1050K			SI5950
JAGUAR	S (433 MHz)	2005-09	1046	71	1050K			
JAGUAR	XF (315MHz)	2009-11	1055	71	1050K			SI5950
JAGUAR	XF (433MHz)	2009-11	1046	71	1050K			
JAGUAR	XJ (315 MHz)	04-'11	1055	71	1050K			SI5950
JAGUAR	XJ (433MHz)	04-'11	1046	71	1050K			
JAGUAR	XK (315MHz)	07-'11	1055	71	1050K			SI5950
JAGUAR	XK (433MHz)	07-'11	1046	71	1050K			
JEEP	COMMANDER	2006-07	1051	71	1050K/ 2030K		7001	SC36AA
* 1051 and 20066 are interchangeable								
JEEP	COMMANDER	2008-10	28155 - SCHR	53	2030K		7004	SI1698
JEEP	COMMANDER	2008-10	1043/DILL	71	1050K		7004	SI1698
JEEP	COMPASS	2007-11	1051/ 20066	71	1050K/ 2030K	33000	7001	SC36AA
* 1051 and 20066 are interchangeable								
JEEP	GRAND CHEROKEE	02-'04	20028	64	1080K	33100	7004	SC90AC
JEEP	GRAND CHEROKEE	05-'07	1051	71	1050K/ 2030K	33000	7001	SC36AA
* 1051 and 20066 are interchangeable								
JEEP	GRAND CHEROKEE	2008-10	28155 - SCHR	53	2030K		7004	SI1698
JEEP	GRAND CHEROKEE	2008-10	1043/DILL	71	1050K		7004	SI1698
JEEP	GRAND CHEROKEE	2011	9398		VS-950			
JEEP	LIBERTY (433Mhz)	2004	20028	64	1080K	33100	7004	SC90AC
JEEP	LIBERTY	05-'06	1051	71	1050K		7001	SC36AA
JEEP	LIBERTY	2007-08	1051/ 20066	71	1050K/ 2030K	33000	7001	SC36AA
* 1051 and 20066 are interchangeable								
JEEP	LIBERTY (433 MHz)	2009	28155 - SCHR	53	2030K		7004	SI1698
JEEP	LIBERTY (433 MHz)	2009	1043/DILL	71	1050K		7004	SI1698
JEEP	LIBERTY	2010	1051/ 20066	71	1050K	33000	7001	SC36AA
JEEP	LIBERTY	2010-11	9308		VS-950		7001	
JEEP	PATRIOT	2007-'11	1051/20066	71	1050K/ 2030K	33000	7001	SC36AA
JEEP	WRANGLER	2007-08	1051/20066	71	1050K/ 2030K	33000	7001	SC36AA
* 1051 and 20066 are interchangeable								
JEEP	WRANGLER	2009-10	28155 - SCHR	53	2030K		7004	SI1698
JEEP	WRANGLER	2009-10	1043/DILL	71	1050K		7004	SI1698

MAKE	MODEL	YEAR	REPL. SENSOR	Torq	KIT #	E-Z SENSOR	Redi Sensor	Orange
JEEP	WRANGLER	2010-11	9308		VS-950		7001	
KIA	AMANTI	2007-'09	28983	31-40	2000K			HY1FA00
KIA	BORREGO	2009	1206-A	31-40	2040K			HY2F000
Note: Use "TRW LoLine Fxd Dly" function on Bartec WRT400 tool to activate sensor on this model								
KIA	FORTE	2010-11	5507		7020K		7001	
KIA	MAGENTIS	2008-10	1068	31-40	59.0340			HY2G200
KIA	MOHAVE	2009	1206-A	31-40	2040K			HY2F000
Note: Use "TRW LoLine Fxd Dly" function on Bartec WRT400 tool to activate sensor on this model								
KIA	OPTIMA HL	2006-'09	1028		59.0340			
	OPTIMA	2011	5507		7020K		7001	
KIA	RIO	2007-'09	1206-A	31-40	2040K			HY2F000
Note: Use "TRW LoLine Fxd Dly" function on Bartec WRT400 tool to activate sensor on this model								
KIA	RIO 5	2008-09	1206-A	31-40	2040K			HY2F000
Note: Use "TRW LoLine Fxd Dly" function on Bartec WRT400 tool to activate sensor on this model								
KIA	RONDO	2006-'09	1068	31-40	59.0340			HY2G200
KIA	SEDONA	2006-'08	1028	31-40	59.0340			HY4D200
KIA	SEDONA	2009-'11	1068	31-40	59.0340			HY2G200
KIA	SORENTO	2007-'09	28983	31-40	2000K			HY1FA00
KIA	SORENTO	2011	5507		7020K		7001	
KIA	SOUL	2010-11	5507		7020K		7001	
KIA	SPECTRA 5	2007-'09	1206-A	31-40	2040K			HY2F000
Note: Use "TRW LoLine Fxd Dly" function on Bartec WRT400 tool to activate sensor on this model								
KIA	SPORTAGE	2006-'08	28983	31-40	2000K			HY1FA00
KIA	SPORTAGE (Lo Line)	2009-11	1206-A	31-40	2040K			HY2F000
Note: Use "TRW LoLine Fxd Dly" function on Bartec WRT400 tool to activate sensor on this model								
KIA	TUSCANY	2007-08	28983	31-40	2000K			HY1FA00
LAND ROVER	LR2	2008-09	TBD	71	1050K			
LAND ROVER	LR2	2010-11	1055	71	1050K			SI5950
LAND ROVER	LR3	2002-05	59.0153	58	*			SPB10A
LAND ROVER	LR3 (315 MHz)	06-'09	1055	71	1050K			SI5950
LAND ROVER	LR3 (433 MHz)	06-'09	1046	71	1050K			
LAND ROVER	LR4 (315 MHz)	2010-11	TBD	71	1050K			SI5950
LAND ROVER	RANGE ROVER (315 MHz)	06-'10	1055	71	1050K			SI5950
LAND ROVER	RANGE ROVER (433 MHz)	06-'10	1046	71	1050K			
LAND ROVER	RANGE ROVER	2010-11		71	1050K			SI5950
LEXUS	ES	2007-11	1204-A	35	1100K	33000		T033011
LEXUS	GS	2005-06	1204-A	35	1100K	33000		T035010
LEXUS	GS	2007-11	1204-A	35	1100K	33000		T033011
LEXUS	GX470	2004-06	1205	35	1110K	33000		T035010
LEXUS	GX470	2006-11	1204-A	35	1100K	33000		T033021
LEXUS	HS	2010	1204-A	35	1100K	33000		
LEXUS	IS	2006	1204-A	35	1100K	33000		T035010
LEXUS	IS	2006-11	1204-A	35	1100K	33000		T033011
LEXUS	LS	2007-10	1204-A	35	1100K	33000		T033011
LEXUS	LX	2005-'11	1204-A	35	1100K	33000		T033011
LEXUS	RX	2006-11	1204-A	35	1100K	33000		T033011
LEXUS	SC430	2002-07	n/a	27	1120K			
LEXUS	SC	2007-10	1204-A	35	1100K	33000		T033011
LINCOLN	AVIATOR	03-'05	20096	44	1060K	33100	7004	SC50BA
LINCOLN	MARK LT	2006-08	1048***		**	33000	7001	
LINCOLN	MARK LT	2009	20315		VS-950	33000	7001	SC9L2T
LINCOLN	MKS	2010	1048***		**	33000	7001	LE6L2T
LINCOLN	MKS	2011	20315		VS-950	33000	7001	SC9L2T
LINCOLN	MKT	2010	1048***		**	33000	7001	LE6L2T
LINCOLN	MKT	2011	20315		VS-950	33000	7001	SC9L2T
LINCOLN	MKX	2007-10	1048***		**	33000	7001	LE6L2T
LINCOLN	MKX	2011	20315		VS-950	33000	7001	SC9L2T
LINCOLN	MKZ	2007-09	1048***		**	33000	7001	LE6L2T
LINCOLN	MKZ	2010-11	20315		VS-950	33000	7001	SC9L2T

MAKE	MODEL	YEAR	REPL. SENSOR	Torq	KIT #	E-Z SENSOR	Redi Sensor	Orange
LINCOLN	NAVIGATOR	03-'04	20096	44	1060K	33100	7004	SC50BA
LINCOLN	NAVIGATOR	05-'06	20135	44	1060K	33000	7001	SC9L2T
LINCOLN	NAVIGATOR	2007-10	1048***		**	33000	7001	LE6L2T
LINCOLN	NAVIGATOR	2011	20315		VS-950	33000	7001	SC9L2T
LINCOLN	TOWN CAR	2008-11	1048***		**	33000	7001	LE6L2T
MAZDA	2	2011	1056	71	1050K		7001	SI140B
MAZDA	3	04-'11	1056	71	1050K		7001	SI140B
MAZDA	5	06-'12	1056	71	1050K		7001	SI140B
MAZDA	6	05-'11	1056	71	1050K		7001	SI140B
MAZDA	CX-7	2007-10	1056	71	1050K		7001	SI140B
MAZDA	CX-9	2007-11	1056	71	1050K		7001	SI140B
MAZDA	MX-5 MIATA	06-'11	1056	71	1050K		7001	SI140B
MAZDA	RX-8	04-'11	1056	71	1050K		7001	SI140B
MAZDA	SPEED 3	2010	1056	71	1050K		7001	
MAZDA	SPEED 6	2007-08	1056	71	1050K		7001	SI140B
MAZDA	TRIBUTE	2006-08	1048***			33000	7001	LE6L2T
MAZDA	TRIBUTE	2009-11	20315		VS-950	33000	7001	SC9L2T
MASERATI	QUATTROPORTE	04-'08	59.0151		*			
MASERATI	QUATTROPORTE	2010-11	9008/BERU					
MASERATI	COUPE	2009	59.0151					
MASERATI	COUPE	07/2009-11	9008/BERU					
MERCEDES	C CLASS (433 MHz)	2007-12	28214	53	2030K			SC9400
MERCEDES	CL CLASS (315 MHz)	07/99-'06	59.0157		*			SPB10B
MERCEDES	CL CLASS	07/99-'07	59.0151		*			SPB10A
MERCEDES	CL CLASS (315 MHz)	2007-'11	1054		1040K - valve			
MERCEDES	CL CLASS (433 MHz)	2007-'11	1049		1040K - valve			
MERCEDES	CL CLASS - SCHRADER	2009-11	28214	53	2030K			SC9400
MERCEDES	CLK CLASS (315 MHz)	2006-07	59.0157		*			SPB10B
MERCEDES	CLK CLASS (433 MHz)	2008-09	28214	53	2030K			SC9400
MERCEDES	CLS CLASS (315 MHz)	2006-11	1054		1040K - valve			
MERCEDES	CLS CLASS (433 MHz)	2006-09	1049		1040K - valve			
MERCEDES	CLS CLASS (433 MHz) - SCHR	2008-10	28214	53	2030K			SC9400
MERCEDES	E CLASS (315 MHz)	07/99-'05	59.0157		*			SPB10B
MERCEDES	E CLASS (433 MHz)	07/99-'05	59.0151		*			SPB10A
MERCEDES	E CLASS (433 MHz)	2006-10	1049		1040K - valve			
MERCEDES	E CLASS (315 MHz)	2006-10	1054		1040K - valve			
MERCEDES	E CLASS (433 MHz) - SCHR	2010-11	28214	53	2030K			SC9400
MERCEDES	G CLASS (433 MHz)	2007-10	28214	53	2030K			SC9400
MERCEDES	GL CLASS (433 MHz)	2007-10	1049		1040K - valve			
MERCEDES	GL CLASS (315 MHz)	2007-10	1054		1040K - valve			
MERCEDES	GL CLASS (433 MHz) - SCHR	2010-11	28214	53	2030K			SC9400
MERCEDES	GLK CLASS (315 MHz)	2010-11	28214	53	2030K			SC9400
MERCEDES	ML CLASS (433 MHz)	2006-10	1049		1040K - valve			
MERCEDES	ML CLASS (315 MHz)	2006-10	1054		1040K - valve			
MERCEDES	ML CLASS (433 MHz) - SCHR	2010-11	28214	53	2030K			SC9400
MERCEDES	R CLASS (433 MHz)	2006-09	1049		1040K - valve			
MERCEDES	R CLASS (315 MHz)	2006-09	1054		1040K - valve			
MERCEDES	R CLASS (433 MHz)	2010	28214	53	2030K			SC9400
MERCEDES	R CLASS (433 MHz)	2011	1049		1040K - valve			
MERCEDES	S CLASS (433 MHz)	07/99-'06	59.0151		*			SPB10B
MERCEDES	S CLASS (315 MHz)	07/99-'06	59.0157		*			SPB10A
MERCEDES	S CLASS (433 MHz)	2007-09	1049		1040K - valve			
MERCEDES	S CLASS (315 MHz)	2007-09	1054		1040K - valve			
MERCEDES	S CLASS (433 MHz)	2010-11	28214	53	2030K			SC9400
MERCEDES	SL CLASS (433 MHz)	07/99-'05	59.0151		*			
MERCEDES	SL CLASS (315MHz)	99-'05	59.0157		*			
MERCEDES	SL CLASS (433 MHz)	2006-09	1049		1040K - valve			
MERCEDES	SL CLASS (315 MHz)	2006-09	1054		1040K - valve			
MERCEDES	SLK CLASS	2008-11	28214	53	2030K			SC9400

MAKE	MODEL	YEAR	REPL. SENSOR	Torq	KIT #	E-Z SENSOR	Redi Sensor	Orange
MERCEDES	SLR CLASS (315 Mhz)	2004-06	59.0157		*			SPB10B
MERCEDES	SLR CLASS (433Mhz)	99- '06	59.0151		*			SPB10A
MERCEDES	SLR CLASS (433 MHz)	2008-09	1049		1040K - valve			
MERCEDES	SLR CLASS (315 MHz)	2008-09	1054		1040K - valve			
MERCURY	GRAND MARQUIS	2008-10	1048***		**	33000	7001	LE6L2T
MERCURY	MARINER	2006-08	1048***		**	33000	7001	LE6L2T
MERCURY	MARINER	2009-11	20315		VS-950	33000	7001	SC9L2T
MERCURY	MILAN	2008-09	1048***		**	33000	7001	LE6L2T
MERCURY	MILAN	2010	20315		VS-950	33000	7001	SC9L2T
MERCURY	MOUNTAINEER	02-'05	20096		1060K	33100	7004	SC50BA
MERCURY	MOUNTAINEER - BAND TYPE	2006-10	1048***		**	33000	7001	LE6L2T
MERCURY	MONTEGO	2008-09	1048***		**	33000	7001	LE6L2T
MERCURY	MONTEREY	2004-05	20096		1060K	33100	7004	SC50AA
MERCURY	MONTEREY	2006-07	1048***		**	33000	7001	LE6L2T
MERCURY	MARINER	2006-08	1048***		**	33000	7001	LE6L2T
MERCURY	SABLE	2008-09	1048***		**	33000	7001	LE6L2T
MINI	ALL	2007-10	1027		*			SPB10A
MINI	ALL	09/09 - 2010+	9012/BERU		*			
MINI	ALL	09/09 - 2010+	9012/BERU		*			
MINI	ALL	09/09 - 2010+	9012/BERU		*			
MITSUBISHI	ECLIPSE (ALLOY)	2006-10	20034	45-53	1080K	33000		SC3081
MITSUBISHI	ECLIPSE (STEEL)	2006-07	20069	45-53	1130K	33000		SCK001
MITSUBISHI	ECLIPSE	2011	1051	71	1050K		7001	
MITSUBISHI	ENDEAVOR	04-'06	20028	45-53	1080K	33100	7004	SC90AC
MITSUBISHI	ENDEAVOR	2006-'11	20034	45-53	1080K	33000		SC3081
MITSUBISHI	GALANT	04-'06	20028	45-53	1080K	33100	7004	SC90AC
MITSUBISHI	GALANT (STEEL)	2007-09	20069	45-53	1130K			SCK001
MITSUBISHI	GALANT (ALLOY)	2007-11	20034	45-53	1080K	33000		SC3081
MITSUBISHI	LANCER	2008-11	1051	71	1080K		7001	SC36AA
MITSUBISHI	MONTERO	03-'05	20034	45-53	1080K	33000		SC3081
MITSUBISHI	OUTLANDER	2007-11	1051	45-53	1080K		7001	SC36AA
MITSUBISHI	RAIDER	2008-09	9154	53	2030K	33000		
NISSAN	350Z	03-'06	20064	45-60	1080K	33000		SCD001
NISSAN	350Z	2007- 09	28204	50-70	2030K	33000	7001	SCA01B
NISSAN	370Z	2009- 11	28204	50-70	2030K	33000	7001	SCA01B
NISSAN	ALTIMA	2006- 11	28204	50-70	2030K	33000	7001	SCA01B
NISSAN	ARMADA - ALLOY	2005-'08	20161	49	1080K	33000		SCK001
NISSAN	ARMADA - STEEL	2005-'06	20069	49	1130K	33000		SCK001
NISSAN	ARMADA - LE	2008-11	28204	50-70	2030K	33000	7001	SCA01B
NISSAN	CUBE	2009-10	28204	50-70	2030K	33000	7001	SCA01B
NISSAN	FRONTIER	2003-04	20064	45-60	1080K	33000		SCD001
NISSAN	FRONTIER - OEM#40700-CK001	05-'08	20161	49	1080K	33000		SCK001
NISSAN	FRONTIER - OEM#40700-CK002	05-'07	20069	49	1130K	33000		SCK001
NISSAN	FRONTIER (STEEL)	2008-11	28204	50-70	2030K	33000	7001	SCA01B
NISSAN	GT-R	2009-11	28204	50-70	2030K	33000	7001	SCA01B
NISSAN	JUKE	2011	28204	50-70	2030K	33000	7001	
NISSAN	LEAF	2011	1216	50-70	1100K			
NISSAN	MAXIMA	2006-'07	20161	49	1080K	33000		SCK001
NISSAN	MAXIMA	2007-11	28204	50-70	2030K	33000	7001	SCA01B
NISSAN	MURANO	03-'06	20064	45-60	1080K	33000		SCD001
NISSAN	MURANO	2007-11	28204	50-70	2030K	33000	7001	SCA01B
NISSAN	PATHFINDER	2003-04	20064	45-60	1080K	33000		SCD001
NISSAN	PATHFINDER (STEEL)	AUG '04	20069	49	1130K	33000		SCK001
NISSAN	PATHFINDER	2005-06	20161	49	1080K	33000		SCK001
NISSAN	PATHFINDER	2007-11	28204	50-70	2030K	33000	7001	SCA01B
NISSAN	QUEST OEM# 40700-CK002	04-'07	20069 - STEEL	49	1130K	33000		SCK001
NISSAN	QUEST OEM# 40700-CK001	05-'07	20161 - ALUM	78	1080K	33000		SCK001
NISSAN	QUEST	2008-09	28204	50-70	2030K	33000	7001	SCA01B
NISSAN	ROGUE	2008-11	28204	50-70	2030K	33000	7001	SCA01B
NISSAN	SENTRA (ALLOY)	2007- 08	20161	75	1080K	33000		SCK001
NISSAN	SENTRA - STEEL	2007- 11	28204	50-70	2030K	33000	7001	SCA01B

MAKE	MODEL	YEAR	REPL. SENSOR	Torq	KIT #	E-Z SENSOR	Redi Sensor	Orange
NISSAN	TITAN OEM# 40700-CK002	04-'05	20069 - STEEL	49	1130K	33000		SCK001
NISSAN	TITAN OEM# 40700-CK001	05-'07	20161 - ALUM	49	1080K	33000		SCK001
NISSAN	TITAN	2007-11	28204	50-70	2030K	33000	7001	SCA01B
NISSAN	VERSA - (ALLOY)	2007- '08	20161	71	1080K	33000		SCK001
NISSAN	VERSA - (STEEL)	2007- '11	28204	50-70	2030K	33000	7001	SCA01B
NISSAN	XTERRA	03-'04	20064	45-60	1080K	33000		SCD001
NISSAN	XTERRA	05-'06	20161	49	1080K	33000		SCK001
NISSAN	XTERRA (STEEL)	06-'07	20069	49	1130K	33000		SCK001
NISSAN	XTERRA	2007-11	28204	50-70	2030K	33000	7001	SCA01B
PLYMOUTH	PROWLER	2000	28004		20012			
PLYMOUTH	PROWLER	2001	28004		20012			
PONTIAC	G3	2009-10	20153		VS-950	33000	7001	SC4101
PONTIAC	G5	2008	20158	62	1070K	33000	7001	SI1013
PONTIAC	G5	2009-10	20153		VS-950	33000	7001	SC4101
PONTIAC	G6 OE#15921013	2008	20158	62	1070K	33000	7001	SI1013
PONTIAC	G6 OE#15922396	2008-10	20153		VS-950	33000	7001	SC4101
PONTIAC	G8	2008-09	20153		VS-950	33000	7001	SC4101
PONTIAC	GRAND PRIX	2007-'08	20158	62	1070K	33000	7001	SI1013
PONTIAC	MONTANA	2008	20158	62	1070K	33000	7001	SC8606
PONTIAC	SOLSTICE	2008-10	20158	62	1070K	33000	7001	SI1013
PONTIAC	TORRENT	2007-'09	20158	62	1070K	33000	7001	SI1013
PONTIAC	VIBE	2008-10	1204-A	35	1100K	33000		T033011
PONTIAC	WAVE	2008-09	20153		VS-950	33000	7001	SC4101
PORSCHE	911 (315MHZ)	2006-08	59.0157	31-40	*			SPB10A
PORSCHE	911 (433MHZ)	2006-08	59.0151	31-40	*			SPB10A
PORSCHE	911 (433MHZ)	2009-10	9008/BERU	31-40	*			
PORSCHE	911 (315MHZ)	2011	59.0157	31-40				SPB10B
PORSCHE	BOXSTER (315MHZ)	2006-08	59.0157	31-40	*			SPB10B
PORSCHE	BOXSTER (433 MHz)	11/2008-11	59.0151	31-40	*			SPB10A
PORSCHE	CARRERA	04-'09	59.0151	31-40	*			SPB10A
PORSCHE	CAYENNE	02-'06	59.0156	31-40	*			
PORSCHE	CAYENNE (315 Mhz)	2009-10	59.0157	31-40	*			SPB10B
PORSCHE	CAYENNE (433 MHz)	2007-11	59.0158	31-40	*			SPB10A
PORSCHE	CAYMAN	2006-'11	59.0151	31-40	*			SPB10A
PORSCHE	PANAMERA (315Mhz)	2010-11	59.0157	31-40	*			SPB10B
PORSCHE	PANAMERA (433Mhz)	2010-11	9008/BERU	31-40	*			SPB10A
ROLLS ROYCE	PHANTOM (433 Mhz)	2007-10	1027	31-40	*			SPB10A
ROLLS ROYCE	CABRIO (433 Mhz)	2007-10	1027	31-40	*			SPB10A
SAAB	9-3	2004-07	28078	62	2010K			
SAAB	9-3	2008-11	28078	62	2010K			
SAAB	9-5	2004-07	28078	62	2010K			
SAAB	9-5	2008-10	20159	62	2010K			
SAAB	9-7X	2005-09	20116	62	1070K		7001	SC4006
SATURN	ASTRA	2008-09	28078	62	2010K			
SATURN	ASTRA	2010	20153		VS-950	33000	7001	SC8826
SATURN	AURA	2007-08	20158	62	1070K	33000	7001	SI1013
SATURN	AURA	Late 08-10	20153		VS-950	33000	7001	SC4101
SATURN	LAMDA CROSSOVER	2007-08	20158	62	1070K	33000	7001	SI1013
SATURN	OUTLOOK	2007-08	20158	62	1070K	33000	7001	SI1013
SATURN	OUTLOOK	2009-10	20153		VS-950	33000	7001	SC4101
SATURN	SKY	2008-09	20158	62	1070K	33000	7001	SI1013
SATURN	VUE	2007-10	20153		VS-950	33000	7001	SC4101
SCION	tc	2006- 11	1204-A	35	1100K	33000		T033011
SCION	xB	2008- 11	1204-A	35	1100K	33000		T033011
SCION	xD	2008-11	1204-A	35	1100K	33000		T033011
SMART	FORTWO - SIEMENS	2008	1049	53	1040K			
SMART	FORTWO	2008-10	28214	53	2030K			SC9400
SUBARU	B9 TRIBECA	2006- '07	20081	66	1080K	33000		SCG00A
SUBARU	FORESTER	2008-11	28203		VS-950	33000		SCG01A

MAKE	MODEL	YEAR	REPL. SENSOR	Torq	KIT #	E-Z SENSOR	Redi Sensor	Orange
SUBARU	IMPREZA	2008-11	28203		VS-950	33000		SCG01A
SUBARU	LEGACY	04- '07	20081	66	1080K	33000		SCG00A
SUBARU	LEGACY	2008-11	28203		VS-950	33000		SCG01A
SUBARU	OUTBACK	04- '07	20081	66	1080K	33000		SCG00A
SUBARU	OUTBACK	2008-11	28203		VS-950	33000		SCG01A
SUBARU	TRIBECA	2008-11	28203		VS-950	33000		SCG01A
SUBARU	WRX	04-07	20081	66	1080K	33000		SCG00A
SUZUKI	EQUATOR	2009-11	28204	68	2030K	33000	7001	SC4101
SUZUKI	FORENZA	2007-08	20153		VS-950	33000	7001	SC4101
SUZUKI	GRAND VITARA	2007-11	20087	80	2010K	33000		SC54J2
SUZUKI	KIZASHI	2010-11	1051	62	1050K		7001	SC36AA
SUZUKI	RENO	2007-08	20153		VS-950	33000	7001	SC4101
SUZUKI	SX4	2007- '11	20087	80	2010K	33000		SC54J2
SUZUKI	VERONA	2005-06	20082	80	2010K	33000		SC4045
SUZUKI	XL-7	2005-06	20087	80	2010K	33000		SC54J2
SUZUKI	XL-7	2007-'10	20158	62	1070K	33000	7001	SC8606
TESLA	ROADSTER	2010	1212	40-50	2020K			
TOYOTA	4RUNNER	03-'05	1205	35	1110K			TC35010
TOYOTA	4RUNNER	2006-11	1204-A	35	1100K	33000		TO33011
TOYOTA	AVALON	07- '11	1204-A	35	1100K	33000		TO33011
TOYOTA	CAMRY	07-'11	1204-A	35	1100K	33000		TO33011
TOYOTA	COROLLA	2007- 11	1204-A	35	1100K	33000		TO33011
TOYOTA	FJ CRUISER	2008-11	1204-A	35	1100K	33000		TO33011
TOYOTA	HIGHLANDER	2007-11	1204-A	35	1100K	33000		TO33011
TOYOTA	LAND CRUISER	2005-11	1204-A	35	1100K	33000		TO33011
TOYOTA	MATRIX	2007-10	1204-A	35	1100K	33000		TO33011
TOYOTA	PRIUS	06-'10	1204-A	35	1100K	33000		TO33011
TOYOTA	RAV4	2006-11	1204-A	35	1100K	33000		TO33011
TOYOTA	SEQUOIA	04-'07	1204-A	35	1100K	33000		TO33011
TOYOTA	SEQUOIA	2008-11	1206-A	35	1100K	33000		TO0C050
TOYOTA	SIENNA	06- 11	1206-A	35	1100K	33000		TO0C050
TOYOTA	SOLARA	06- '08	1204-A	35	1100K	33000		TO33011
TOYOTA	TACOMA	05-'11	1204-A	35	1110K	33000		TO33011
TOYOTA	TUNDRA	05-'06	1204-A	35	1110K	33000		TO33011
TOYOTA	TUNDRA	2006-11	1206-A	35	1100K	33000		TO0C050
TOYOTA	VENZA	2009-11	1204-A	35	1100K	33000		TO33011
TOYOTA	YARIS	07- '11	1204-A	35	1100K	33000		TO33011
VW	BEETLE	2008-11	1053	71	1030K			SI253D
VW	CC	2009-11	1053	71	1030K			SI253D
VW	EOS	2007- '11	1053	71	1030K			SI253D
VW	GLI	2008-09	1053	71	1030K			SI253D
VW	GOLF	2010-11	1053	71	1030K			SI253D
VW	GTI (Standard Hex Nut)	2006-'11	1053	71	1030K			SI253D
VW	GTI (O- Ring Style Nut)	2006- '07	1041	71	1031K			SI253D
VW	JETTA	06-'11	1053	71	1030K			SI253D
VW	PASSAT (Standard Hex Nut)	06-'10	1053	71	1030K			SI253D
VW	PASSAT (O- Ring style Nut)	06-'08	1041	71	1031K			SI253D
VW	PHAETON (433Mhz)	02-'07	59.0151	35	*			SPB10A
VW	PHAETON (315 Mhz)	03-'07	59.0157	35	*			SPB10B
VW	PHAETON	2007-10	59.0158	35	*			
VW	PHAETON (433Mhz)	2011	9011	35				SOB10A
VW	R32	2008-10	1053	71	1030K			SI253D
VW	RABBIT (Standard Hex Nut)	2006-10	1053	71	1030K			SI253D
VW	RABBIT (O- Ring style Nut)	2006- '07	1041	71	1031K			
VW	ROUTAN	2009-10	1043	71	1050K		7004	SI1698
VW	ROUTAN	2011	9398					
VW	TIGUAN	2009-11	1053	71	1030K			SI253D
VW	TOUAREG	02-'06	59.0156	35	*			SPB10A
VW	TOUAREG	07-'10	59.0158	35	*			SPB10A

MAKE	MODEL	YEAR	REPL. SENSOR	Torq	KIT #	E-Z SENSOR	Redi Sensor	Orange
VW	TOUAREG	2011	9011	35				
VOLVO	C30	2007-11	1044	71	1050K			SC0297
VOLVO	C70	2007-11	1044	71	1050K			SC0297
VOLVO	S40	2007-11	1044	71	1050K			SC0297
VOLVO	S60	04-'10	20156	44	2010K			SC8991
VOLVO	S60	2011	1044	71	1050K			SC0297
VOLVO	S80	04-'07	20156	44	2010K			SC8991
VOLVO	S80 (433 MHz)	2007-'11	1044	71	1050K			SC0297
VOLVO	V50	2008-11	1044	71	1050K			SC0297
VOLVO	V70	04-'07	20156	44	2010K			SC8991
VOLVO	V70 (433MHz)	2008-10	1044	71	1050K			SC0297
VOLVO	XC60	2009-10	20156	44	2010K			SC8991
VOLVO	XC60	2011						
VOLVO	XC70	04-'07	20156	44	2010K			SC8991
VOLVO	XC70	2008-11	1044	71	1050K			SC0297
VOLVO	XC90	2005-11	20156	44	2010K			SC8991

* Beru Replacement stems determined by overall length of the stem

** Banded Style Sensor - 1194/Dill is the replaceable/ adjustable band

*** 1048 Banded sensor comes as optional kit 5105 w/ Band, Metal Cradle, 2 Plastic Clips and 1 1048 Sensor

**** Indicates 2- piece sensor

59.0307 = 48m 59.0337 = 43mm

59.0357 = 51r 59.0387 = 49mm

65A INDUSTRIAL PARK ROAD HINGHAM, MA 02043 PHONE:800.242.1446 FAX:800.982.9556

9330 INDUSTRIAL TRACE ALPHARETTA, GA 30004 PHONE:800.666.6464 FAX:877.664.1290